


Completed Works Report

FAO :-

Ref :-

Further to us attending the above property on 15th October 2019, we can confirm that works are complete as shown in the pictures below. All foul drainage Assets cleaned, grout removed, manholes washed down and system re-surveyed to confirm condition.

Site plan of drainage surveyed and cleaned.



43 High Street, Uppermill, Oldham, Greater Manchester. OL3 6HS.

Tel : 0161-366-1067 Email : Info@ftds.co.uk


Company Registration No : 10872764.



MH06-MH05



MH05-MH04



MH04-MH03



MH03-MH02



MH03-MH01



MH06 Pre Clean p- Concrete in bottom of MH.



MH06 Post Clean – All running clear.

43 High Street, Uppermill, Oldham, Greater Manchester. OL3 6HS.

Tel : 0161-366-1067 Email : Info@ftds.co.uk

Company Registration No : 10872764.



All lines have been cleaned and all debris removed from each manhole and drainage run.

The system has a small dip in the pipe outside No 27 for around 4m where the water is sitting but this is still now flowing well.

We found that there were a significant number of wipes in these lines so would suggest a letter drop to all residents making them aware of the issues that flushing these causes.

A DVD will be posted out with all CCTV clips of each asset and pipe condition can be seen but we found no pressing issues now that all concrete/grout had been removed.

Should you require any further information or clarification then please feel free to contact us.

Many Thanks,

First Time Drainage Solutions Ltd (FTDS Ltd)